


# Removing Removing The CPU Die

Follow the steps in

- Legend 4-1
- Legend 5-1,
- Legend 9-1;

before proceeding as below. Reverse the procedure to assemble CPU die.



## Legend 10-1:

- Use a flat screwdriver to loosen the CPU die in anticlockwise direction as shown by **#1**.
- Remove the CPU die as shown by **#2**.

## To restore the system back to its assembled situation:

- Reverse the steps in **Legend 10-1**.
- Reverse the steps in **Legend 9-1**.
- Reverse the steps in **Legend 5-1**.
- Reverse the steps in **Legend 4-1**.